

Dolan Chemical Laboratory 4001 Bixby Road Groveport, OH 43125 T: 614-836-4221, Audinet 210-4221 F: 614-836-4168, Audinet 210-4168 http://aepenv/labs

Water Analysis

Location: Mountaineer Plant Report Date: 8/5/2013

1	st	Si	ta	ae	Fee	þ£

Sample Number:	133007-001	Date Col	lected:	07/23/2013	08:00	Date Received: 7/2	24/2013
Parameter		Result Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		213 ug/L	0.50	0.20	DPC	07/31/2013 13:07	EPA 200.8

## 2nd Stage Feed

Sample Number:	133007-002		Date Co	llected:	07/23/2013	08:00	Date Received: 7/2	24/2013
Parameter		Result	Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		16.3	ug/L	0.50	0.20	DPC	07/31/2013 13:11	EPA 200.8

## **Bioreactor Effluent**

Sample Number:	133007-003		Date Co	ollected:	07/23/2013	08:00	Date Received: 7/2	24/2013
Parameter		Result	Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		1.5	ua/L	0.50	0.20	DPC	07/31/2013 13:16	EPA 200.8

Brian Snyder, Chemist II

Email bssnyder@aep.com Tel. 614-836-4224

Fax 614-836-4168 Audinet 210-4224

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.